

From: [Sanchez, Carlos](#)
To: [Miller, Garyg](#)
Cc: [Meyer, John](#); [Coltrain, Katrina](#)
Subject: Re: SJRWP Update 9/9/2017
Date: Saturday, September 09, 2017 6:28:02 PM

Great
Thanks Gary

Sent from my iPhone

> On Sep 9, 2017, at 6:10 PM, Miller, Garyg <Miller.Garyg@epa.gov> wrote:
>
> Carlos,
>
> Continued cap repair work under EPA oversight – on western cell & central berm (1st picture).
> Continued manual cap probing under oversight of EPA Dive Team representative – eastern cell (2nd picture).
> Temporary fence (3rd picture).
> EPA investigated black material on western cell reported by Scott Jones – found what appeared to be mold (4th picture). Sediment in this area will be sampled on Monday for dioxins/furans.
> EPA Dive Team is planning to be ready to enter water on Monday at 10 am to assess NW area of cap. Dive boat will be provided by PRPs.
> Work at the site will resume on Monday 9/11/17.
>
> Regards,
>
> Gary Miller
> Remedial Project Manager
> EPA Region 6 Superfund Division, TX/Ark Section
> 214-665-8318
> miller.garyg@epa.gov
>
> <SJRWP - Repairing Cap 9-9-17.jpg>
> <SJRWP - Manual Probing West Cell 9-9-17.jpg>
> <SJRWP - Temp Fence 9-9-17.jpg>
> <SJRWP - Black Material Western Cell 9-9-17.jpg>